



Golam,

We have been back from Airlie with our new (to us) trimaran. Your prop performed very well with speeds around 10 knots although this was only done to test the motor/prop combination and the motor was brand new. At approx 2800rpm the boat happily motors along at 8.5k to 9k which was ample. For the whole trip (Airlie Beach to Sandgate) of some 85 hours of motoring our average was in excess of 8 knots and fuel consumption around 3 litres per hour.

It would seem that the 3 blade varifold was/is matched very well to the motor output. There is no vibration whatsoever and it is the first time this has been the case on any of the 3 boats we have owned.

Thanks for your help and service in organizing manufacture and delivery.

William Fea

DTZ Australia (Queensland) Pty Ltd

Brisbane Qld 4000
